

# High Speed Vertical Machining Center With APC



## 高速立式加工中心機附交換工作台



### VMC-855+APC


X, Y, Z Axis Travel 800x500x450 mm

- 180° rotary type pallet change.
- Linear ways on 3 axes.
- 10,000 belt-drive spindle (standard).
- 12,000 / 15,000 rpm direct-drive spindle (optional).
- BT 40 spindle taper.
- 24 tools arm type ATC (standard).
- 24 tools fast arm type ATC (optional).
- 32 tools chain type ATC (optional).
- Full splash guard.
- Screw type and link type chip conveyor (standard).

### VMC-855+APC


X, Y, Z軸行程800x500x450 mm

- 180°迴轉交換工作台。
- 三軸線軌。
- 10,000皮帶式主軸為標準。
- 12,000及15,000直結式主軸為選購。
- 主軸錐度BT 40。
- 24把刀刀臂式自動換刀系統為標準。
- 24把刀快速自動換刀系統為選購。
- 32把刀鏈條式自動換刀系統為選購。
- 全密閉式護罩。
- 螺旋式及鏈板式除屑輸送機為標準。



自動交換工作台  
Automatic Pallet Change(APC)

- High accuracy pallet positioning is achieved through 4 positioning cones.
- Air blast clean the positioning cones before pallet is located to ensure accuracy.
- An auto door is provided on the pallet changing system to prevent contamination by chips or fluid.
- Pallet rotation is driven by servo motor.



## VMC-855+APC

**Rapid Traverse** X,Y Axis 48m/min  
Z Axis 32m/min

**快速進給** X,Y 軸 48米/分  
Z 軸 32 米/分

3軸線軌  
3 Axes Linear Ways